FIELD INSPECTION REPORT

Date of Inspection :	23.12.2020	District: Gopalganz	
Division: Llastina		Length (km): 11891 KM	
Name of the Road: Ha	thua- Kusaudi	i Road to Bigahi Baris	sal
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
CI No.	Parameters	to be checked	Remarks

SI. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/Je	
b)	Condition of Surfacing	20 U	
c)	Riding Quality	,8/U V	
d)	Road Camber	S/J&	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/M6	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U SR	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U M	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	y €s/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	U

(Signature) (Signature)

NAME: M-S. Siddigi

DESIGNATION: DE