FIELD INSPECTION REPORT

		ALTON EX	TION REPORT	1	
Date of Inspection: 241		24/12/20	District:	valanda	
Division :		Rogger	Length (km):	MADORN	
	he Road:	N.4-31 to		1 2212	
Scheme/Programme: Package No.:		MAINTENANCE	V	iontine	
			Road Id No.:	-	
Status of the Project: Work is a case of:		The second secon	Ongoing/Completed/Under Maintenance		
Sl. No.		COLUMN THE RESIDENCE OF THE PARTY OF THE PAR		Remarks	
		Parameters to	be checked	Keman	
1.	Pavement			Charles and the	
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			SAU	
c)	Riding Quality			SAU	
d)	Road Camber			S/U_	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
(1)	Contraction Joints provided or not (CC Pavement)			Yes/No N.	
g)	Compaction of flank/slope & raincuts if any			YesANo	
2.	Cross Drainage			No.	
a)	Condition of head walls in Hume pipe culverts including its painting			ing S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/eautionary Board/km & 200m stones/Pavement road markings are provided and maintained			00m Yes/No	
-4.4.	Compliance History			A CONTRACTOR	
a)	Status of ATR's & any others			No	
Over	II Rating				
Overall reasing			Satisfactory (S) Satisfactory but requires Improvement (SRI)		
		Satisfactory b Unsatisfactor		I) SRI	

Salowort Current

(Signature) EN112/22

NAME: