FIELD INSPECTION REPORT

Date of Inspection: 22/12/2020	District: Samastipur	
Division: RWD Dalsinghsarai	Length(km): 3-8	er
Name of Road: LO43 to Keru	2-1 2-1	3
Scheme / Programme: MAINTENANCE	Pm/- PM	
Package No: BR-30R ~ 498	Road Id No:	
Status of the Project: Ongoing/Completed/U	nder Maintenance	
Work is a case of: New Connectivity/	Up gradation/ Maintenance	
No Parameters to		Remarks
Pavement		
Road Junction Condition		1 3
Condition of Surfacing		9
) Riding Quality	NEW TOTAL PROPERTY.	3
) Road Camber	BANK BURGANIER	3
Whether free from defects such as visible aggregates in case of CC Pavement	e cracks, exposed	S
Construction Joint provided or not(CC Pa	avement)	
Compaction of flank/slope & raincuts if a	anv	
Cross Drainage		SRI
Condition of head walls in Hume pipe cu including its painting	lverts	S
Condition of Abutment & Wing walls, S	lab in RCC culverts	
Condition of railings/slab/approach for Br	ridge	S
Road Furniture		
Whether sign boards/information/cautiona stones/Pavement road markings are provided	ary Board/km & 200m ded and maintained	R.I
Compliance History		
Status of ATR's & any others		
		NO

Overall Rating:

SRI

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

(Signature)

Rament Kumor Syl

NAME:

DESIGNATION: