0

FIELD INSPECTION REPORT

| Lanner | | TION TILL ON | |
|-------------|---|----------------------|--------------|
| Da | te of Inspection: 24.12.2020 | District: Samastipur | |
| DI | vision: RWD Dalsinghsarai | Length(km): 1. are | lan |
| Na | me of Road: 4039 MDR to Bazipur | mean' Dalk shin | mle. |
| 201 | ieme Programme: MAINTENANCE | | |
| - | kage No: BR 30 F 56. | 2 Road Id No: | |
| Sta | tus of the Project: Ongoing/Completed/Under Ma | intenance | |
| STORY STORY | rk is a case of: New Connectivity/ Up grad. | ation/ Maintenance | |
| SI. | Parameters to be Chec | ked | Rem: ks |
| | Pavement | | |
| 1) | Road Junction Condition | | 9 |
|)) | Condition of Surfacing | | 5 |
|) | Riding Quality | | 9 |
|) | Road Camber | | <i>S S S</i> |
| + | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement | | 9 |
| | Construction Joint provided or not(CC Pavement) | | 5 |
|) | Compaction of flank/slope & raincuts if any | | 5 |
| | Cross Drainage | | |
| | Condition of head walls in Hume pipe culverts including its painting - | | 5 |
| | Condition of Abutment & Wing walls, Slab in RO | CC culverts | |
| | Condition of railings/slab/approach for Bridge | | |
| | Road Furniture | | |
| | Whether sign boards/information/cautionary Boardstones/Pavement road markings are provided and in | | 5 |
| (| Compliance History | | |
| 8 | Status of ATR's & any others | | M |
| - | | | |

Overall Rating :

| Satisfactory(S) | 3 |
|--|---|
| Satisfactory but requires Improvement(SRI) | |
| Unsatisfactory(U) | |

(Sign: ire)

NAME: Amil production: