FIELD INSPECTION REPORT

	te of Inspection: 2//12/2020	District: Samastipur	_	
	vision: RWD Dalsinghsarai	Length(km): 3.53	_	
	me of Road: TO 3 to	mustatabur		
	ieme / Programme: MAINTENANCE	pmosy		
_	kage No: BR-30R-508	Road Id No:		
Stat	tus of the Project: Ongoing/Completed/Under	Maintenance		
Work is a case of: New Connectivity/ Up gradation/ Maintenance				
No	Parameters to be C	hecked Remarks		
	Pavement			
)	Road Junction Condition	\$		
)	Condition of Surfacing	8		
)	Riding Quality			
)	Road Camber	S		
	Whether free from defects such as visible cracaggregates in case of CC Pavement	cks, exposed		
	Constraction Joint provided or not(CC Pavement	ent)		
	Compaction of flank/slope & raincuts if any	R-I		
	Cross Drainage	R+L		
	Condition of head walls in Hume pipe culverts including its painting	5-/		
	Condition of Abutment & Wing walls, Slab in	RCC culverts		
	Condition of railings/slab/approach for Bridge	. /		
	Road Furniture			
	Whether sign boards/information/cautionary Bestones/Pavement road markings are provided as	oard/km & 200m		
Compliance History				
1	Status of ATR's & any others			
(Overall Rating : SRI	NO		
	Satisfactory(S)			
	Satisfactory but requires In	(CDT)		

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

Rameth Kumor Synh

(Signature)

(Delle

NAME:

DESIGNATION: