## FIELD INSPECTION REPORT

_	te of Inspection: 21.12.2020	District: Samastipur		
D' ' ' DIVID D I I I		Length(km): 1.0		
Nar	ne of Road: Mardhobur Maharo	leo morth to Kush	waha + la	
	eme / Programme: MAINTENANCE	GT SI	14	
		INOAU IU INO:		
Stat	rus of the Project: Ongoing/Completed/Under	Maintenance		
	rk is a case of: New Connectivity/ Up g	gradation/ Maintenance		
SI. No	Parameters to be C		Remarks	
1	Pavement			
a)	Road Junction Condition		3	
b)	Condition of Surfacing		9	
c)	Riding Quality		S	
d)	Road Camber		S	
e)	Whether free from defects such as visible cra aggregates in case of CC Pavement	icks, exposed	S	
f)	Constraction Joint provided or not(CC Paven	nent)		
g)	Compaction of flank/slope & raincuts if any		R.T	
2	Cross Drainage		V. Z	
a)	Condition of head walls in Hume pipe culver including its painting	ts		
)	Condition of Abutment & Wing walls, Slab	in RCC culverts	M-XI.	
:)	Condition of railings/slab/approach for Bridg	e		
}	Road Furniture			
1)	Whether sign boards/information/cautionary stones/Pavement road markings are provided	Board/km & 200m and maintained	R.I	
	Compliance History			
)	Status of ATR's & any others		No	
	Overall Rating :	R-I	7 (0	

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

Ramest Kumar Sth

(Signature)

NAME:

DESIGNATION: