FIELD INSPECTION REPORT

Division :		Pargery	District: Malando Length (km): 200 400 6	STOWN 1
			Jabaha to Palaction	interace
	rogramme:	MAINTENANCE	100000000000000000000000000000000000000	
Package No.: Status of the Project:		Ongoing/Comple	the location of	
		New Connectivity	New Connectivity/Up gradation/ Maintenance	
Sl. No.				Remarks
1.	Payement			A STATE OF THE STA
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			Ş/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No_
f)	Contraction Joints provided or not (CC Pavement)			Yes/Non-
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			AND AND AND ASSESSED.
a)	Status of ATR's & any others			No.
Overel	Rating			
Overal	Rating	Satisfactory (2
		Satisfactory l Unsatisfactor	out requires Improvement (SRI)	

Salcust Kuman

(Signature) X

NAME: