

FIELD INSPECTION REPORT

Date of Inspection: 24/12/20
 Division: Arora
 Name of the Road: Harla Fitch Road
 Scheme/Programme: MAINTENANCE
 Package No.:
 Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	Yes
b)	Condition of Surfacing	Yes
c)	Finishing Quality	Yes
d)	Road Camber	Yes
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & re-incuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	Yes/No
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	Yes/SRI/U
c)	Condition of railings/slab/approach for Bridges	Yes/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)


Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

24/12/20
 (Signature)

NAME: Manish Kumar



Shot on Y12
 VIVO AI camera