0

FIELD INSPECTION REPORT

| Personal Personal | | | | | |
|---|--|------------------------|-----------------------|---------|--|
| Date of Inspection: 19.12-2020 District: Samastipur | | | | | |
| Div | ision: RWD Dalsing | thsarai` | Length(km): 0 626 | Kin | |
| Nan | ne of Road: Lo | 48 to Uttar Toli | a | | |
| Sch | eme / Programme: | MAINTENANCE | | | |
| Pac | kage No: | | | | |
| | | ngoing/Completed/Under | Maintenance | | |
| - | rk is a case of: | New Connectivity/ Up g | radation/ Maintenance | | |
| SI. No | Parameters to be Checked | | | Rem: ks | |
| 1 | Pavement | | | | |
| a) | Road Junction Condition | | | 3 | |
| b) | Condition of Surfacing * | | | 2 | |
| c) | Riding Quality | | | S | |
| d) | Road Camber | | | 3 | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement | | | | |
| f) | Construction Joint provided or not(CC Pavement) | | | 4.4 | |
| g) | Compaction of flank/slope & raincuts if any | | | 8 | |
| 2 | Cross Drainage | | | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | | | 5 | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | | | |
| c) | Condition of railings/slab/approach for Bridge | | | | |
| 3 | Road Furniture | | | | |
| a) | Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | s | |
| 4 | Compliance Histor | у | | | |
| 1) | Status of ATR's & a | ny others | | N | |

Overall Rating :

| Satisfactory(S) | | |
|--|---|--|
| Satisfactory but requires Improvement(SRI) | S | |
| Unsatisfactory(U) | | |

(Night 111)

NAME: And Presco