FIELD INSPECTION REPORT

-		FIELD INSPECT			
Date of Inspection: 81/12/020		District: Buxas			
Division: RWD, Buxas			Length (km): 1.300 K	14	
Name of t	he Road:	TO3 to Nagarpu	ra		
	rogramme:		HUBSY (SC)		
Package I			Road Id No.:		
Status of the Project: Ongoing		Ongoing/Completed/U	Inder Maintenance	and the second second second	Problem States of the States o
What was a life or warm to respect to the same		And the second of the Second of the Second S	New Connectivity/Up gradation/ Maintenance Parameters to be checked		Remarks
SI. No.		Parameters to D	e enecked		
1.	Pavement				√ 8/U
a)	Road Junction condition				112
b)	Condition of Surfacing				√ \$/U
c)	Riding Quality			Agazzan garida (grandenses)	S/UV
d)	Road Camber				₩/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No
<u>(1</u>	Contraction Joints provided or not (CC Pavement)				Yes/No
g)	Compaction of flank/slope & raincuts if any				Yes/No
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U
c)	Condition of railings/slab/approach for Bridges				S/SRI/U
3,	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200n stones/Pavement road markings are provided and maintained			200m	Yes/No
4.	Compliance l	History			
(a)		s & any others			NO
0	Rating :	Satisfactory (S)			
Overall I		Catinfactory but re	quires Improvement (\$	RI)	SRI
Overall	# 1	Unsatisfactory (U)			,