

732635
37.35998
4.69m
2m
-2020 14:17

Name of Inspection BA 111029		District: Paveram	
Location: R. V. De Sa - Paveram		Length (km): 2.30 km	
Name of the Road: Paveram		Survey No.: 1014	
Scheme/Programme: RASHTREEYI		Road Id No.:	
Package No.:		Origin: Completed Under Maintenance	
Status of the Project:		New Connectivity Up gradation/Minor	
Work in a state of:		Parameters to be checked	
Sl. No.	Remarks		
1.	Pavement		
a)	Road Junction condition	Good	
b)	Condition of Surfacing	Good	
c)	Grading Quality	Good	
d)	Road Camber	Good	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Good	
f)	Construction Joints provided or not (CC Pavement)	Good	
g)	Compaction of flank slope & rainwater if any	Good	
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRU	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRU	
c)	Condition of railings slab approach for Bridges	S/SRU	
3.	Road Furniture		
a)	Whether sign boards/informatory Board/km & 200m stones/Pavement road markings are provided and maintained	Good	
4.	Compliance History		
a)	Status of ATRs & any others		
Overall Rating		Satisfactory (S)	
		Satisfactory but requires Improvement (SRI)	
		Unsatisfactory (U)	