## FIELD INSPECTION REPORT

Date	of Inspection 1 2	7-12-26-20	District: East champeren		
Divi	sion: dverof		Length (km): 0. 600		
National Property lies		Riam Tell' To	Lesa		
	me/Programme:	MAINTENANCE			
Package No.: Road Id No.: 3170831800					
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance			
BOOMER	WIND THE PARTY OF	THE RESERVE TO SHARE		7	
51. No		Parameters (	in Be-cheekled	Remark	
Ibs	Pavement				
4)	Road Junction	condition		S/U	
b)	Condition of Surfacing		S/U		
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
0)		from defects suc se of CC Pavement.	h as visible cracks, exposed	Yes/No	
1)	Contraction Joints provided or not (CC Pavement) Yes				
g)	Compaction of flank/slope & raincuts if any Yes				
17.14	Comp Destinage	COM AND STREET			
4)	PERSONAL PROPERTY AND PROPERTY AND PERSONAL		e culverts including its painting	SSRIV	
b)	Condition of Abu	tment & Wing walls	s, Slab in RCC culverts N/A	S/SRI/U	
c) .	Condition of rails	ngwsiab/approach fo	r Bridges NA-	S/SRI/U	
	Road Farmiture				
0	Whether sign bo stones/Pavement r	ards/informatory/ca oud markings are pr	utionary Board/km & 200m	Yester .	
	Compliance Ast	n in the	<b>建筑市政协和</b>		
) [2	Status of ATR's &	any others		No	

Overall Rating

Satisfactory (S)	SRI		
Satisfactory but requires Im			
Unantisfactory (U)		-	

NUMBERS has been given to Contrastic

(Signature)

NAME: Harandon Son

DESIGNATION: AE AUD.

Scanned with CamScanner