

FIELD INSPECTION REPORT

Date of Inspection: 27/12/20 District: Purnia.
 Division: Dumdaha Length (km): 4.942
 Name of the Road: LUSA to Baidina (Amay)
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.:

Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	/ S/U
b)	Condition of Surfacing	/ S/U
c)	Riding Quality	/ S/U
d)	Road Camber	/ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No /
f)	Contraction Joints provided or not (CC Pavement)	Yes/No /
g)	Compaction of flank/slope & raincuts if any	Yes/No /
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U /
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U /
c)	Condition of railings/slab/approach for Bridges	S/SRI/U /
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	/ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	/

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

Shailendra Kaur
 ATE

(Signature)
 27/12/20