


# FIELD INSPECTION REPORT

Date of Inspection : 20.12.2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 1.130 KM	
Name of the Road : PMGSY road Sahpur Hat to Gaderi tola via Midgaid			
Scheme / Programme :			
Package No. : MMGSY		Road Id No. : 20703201331	
Status of the Project :   Ongoing / Completed / Under Maintenance			
Work is a case of :   New Connectivity / Up gradation / Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	<b>Pavement</b>		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes / No	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes / No	
g)	Compaction of flank/slope & raincuts if any	Yes / No ✓	
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	NA
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	NA
3.	<b>Road Furniture</b>		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	✓ Yes / No	
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others	NO	
<b>Overall Rating</b>			
	Satisfactory (S)	1	
	Satisfactory but requires Improvement (SRI)	SRI	
	Unsatisfactory (U)	1	

Note: (i) Logo board not painted properly (ii) No painting in H.p culvert (iii) C.C. crust damage in some part

NAME : Ratishwar Rajan  
DESIGNATION : AE

  
 20.12.2020  
 Signature **AE**