Black-Changai

FIELD INSPECTION REPORT

	and the same	COLOTASTA HON REPOR		
1	Date of Inspection : District: Buxar		NOY	
	Division	1: Dumyany Length (lon):	2.01541	
-	The Road: Amount Nahar hulden Nellahia		bur 070 1711	
		Park MMGSY(SC)		
	Package No.: Road Id No.:  Status of the Project: Ongoing Completed Index Maintenance			
	The second secon	Work is a case of: New Connectivity/Up gradation/ Maintenance		
ì	Sl. No. Parameters to be checked		Remarks	
	1.	Pavement	Remarks	
	-			
	(a)	Road Junction condition	LX1	
	b)	Condition of Surfacing	180	
	0)	Riding Quality	Upt .	
	di	Road Camber	5/0	
***************************************	c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement,		
-	A	Contraction Joints provided or not (CC Pavement) Yes No		
-	g)·	Compaction of Bank slope & raincuts if any		
-	2	Gross Drainage		
1	a)r :	Condition of head walls in Hume pipe culverts including its painting S. SRIO		
1	b)	Condition of Abutment & Wing walls, Slab in RCC o	ulverts ( SSRIA NIA	
1	(c)	Condition of railings/slab/approach for Bridges	SSRD -	
A. A.	3.	Road Furniture		
	a)	Whether sign boards/informatory/cautionary Board stones/Pavement road markings are provided and markings are provided and markings.	J/km & 200m   VisiNo	
1	4. Compliance History		1	
-	a)	Status of ATR's & any others	No	
-				
Overall Rating :		Satisfactory (5)	SS	
		Satisfactory but requires Improv	ement (SRI)	
		Unsatisfactory (U)		

NAME:

(Signature)

DESIGNATION: