## FIELD INSPECTION REPORT

Date of I	nspection: 99-1	9-9020 District: Nalanola	
Division	: RWD Harm	aut Length (km): p. 200 Km	
	the Rond: 706	to Imangan,	
		ITENANCE U	
Package		Road Id No.:	ta project
		ng/Completed/Under Maintenance Connectivity/Up gradation/ Maintenance	
		the second secon	Remarks
Sl. No.	P	arameters to be checked	Remarks
1.	Pavement		
n)	Road Junction conditi	S/U	
b)	Condition of Surfacin	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.,,	Cross Drainage	a	
a)	Condition of head wa	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign board stones/Pavement road	Yes/No	
4.	Compliance History		
a)	Status of ATR's & a	ny others	

**Overall Rating** 

Satisfactory (S)	3	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

(Signature) 92

NAME: Cosium Ko malorora

DESIGNATION: JE

Scanned with CamScanner