Block-Chaugai FIELD INSPECTION REPORT Date of Inspection : District: Buxay Division : Dum rag Length (km): Name of the Road: Koransan Changai bath & Rambur Nahartak Banjarya Ko mm GISY (Package No.: Hotel Road Id No.: Status of the Project: Ongoing Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance St. No. Parameters to be checked Remarks 1. Pavement Road Junction condition 113 WU Condition of Surfacing b SIL 0) Riding Quality Sett (1) Road Camber SHE Whether free from defects such as visible cracks, exposed 2) Yes No aggregates in case of CC Pavement. n Contraction Joints provided or not (CC Pavement) Yes Va g)-Compaction of flank/slope & raincuts if any Yes 10 Gross Drainage 2) Condition of head walls in Hume pipe culverts including its painting SISRIU 6) Condition of Abutment & Wing walls, Slab in RCC culverts SISRIAL Condition of railings/slah/approach for Bridges c) S/SREU 3. Road Furniture

Whether sign boards/informatory/cautionary Board/km & 200m

stones/Pavement road markings are provided and maintained

Overall Rating

Compliance History

Status of ATR's & any others

a)

2)

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

NAME: JC

DESIGNATION:

(Signature)

Ves No

Anho