Block-Changai

FIELD INSPECTION REPORT

STATE OF STREET	of Inspection : Distric	District: Buxar		
Divisi	aun: Dum kaon	on		#
Schen Packa	ne/Programme: MAINTINANCE CITY	Harizontola tak	7	A COLUMN
Status of the Project: Ongoing/Completed/Under Mangiegatice				
	is a case of: New Connectivity/Op gradate	initienance	1 1 1 1 - 1	
St. No	l. No. Parameters to be cheeked		Remarks	7
1	Pavement			
a)	Road Junction condition		VI	
bi	Condition of Surfacing		USIL	
(0)	Riding Quality		- Juli	
-di	Road Camber		U8/10	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Susse	
0	Contraction Joints provided or not (CC Pavement)		Yes-No	
g)	Compaction of flank/slope & raincuts if any		Yes No	
2.	Cross Drainage			
(a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/L	5
6)	Condition of Abutment & Wing walls, Slab in RCC culverts		SISRIT	MA
c)	Condition of railings/slab/approach for Bridges		S/SRL1.	1
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		UKNO	
4.	Compliance History			
a)	Status of ATR's & any others		No	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

SIES

72/10/20

(Signature)

NAME:

DESIGNATION:

As miliono