## FIELD INSPECTION REPORT

	Inspection: 20.12.020   District: Bhagalpur		
rision	Bhagalpur   Length (Km):		
ne of	the Road: PM GSY Bagwari Road to	Kohsa	
eme	/ Programme :		
kage	No.: MM (1) > 1 Road ld No.: 207	32120	28
us of	the Project:   Ongoing / Completed / Under Maintenance		
rk is	a case of:   New Connectivity / Up gradation / Maintenance	ce	
. No.		Remarks	
١.	Pavement		
a)	Road Junction condition	VS/U	
b)	Condition of Surfacing	V8/U	
)	Riding Quality	USIU	
}	Road Camber	V5/U	
)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Ves/No	
)	Contraction Joints provided or not (CC Pavement)	Vies/No	
	Cpmpaction of flank/slope & raincuts if any	Yes/NoV	
	Cross Drainage		
	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	
	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
	Road Furniture		•
	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	
	Compliance History		
	Status of ATR's & any others	No	
Ra	ating:		-
1	Satisfactory (S)	1	
	Satisfactory but requires Improvement (SRI)	SPI	
	Unsatisfactory (U)		
	logo board not properly freus	1	B.T &

NAME: Rufleisher Parjak

DESIGNATION : A-E

Signature AE