Inspection Report for Flood Damage Work

Date

- 1 Name of PIUs- Cryan vibrarar Name of Block/Road- Kaysa / machepura to Schizandih Name of PIUs-2
- A For Road
- 1 Damage Location/Chainage 2.50 KM
- 2 Damage Length 21.70m (0.0217 km)
- Nature of Damage 3
- 4 Details of Restoration Works-
 - Material being used in Restoration Works- Brick buts & local sand i
 - ii Equipments/Tools being used in Restoration Works-
 - iii Procedure Taken up in Restoration Works-
 - iv Restored Length - 0:0217 ICM
- B. For Bridge
 - 1 Damage Location/Chainage
 - 2 Damage Length
 - 3 Nature of Damage
 - 4 Details of Restoration Works-
 - Material being used in Restoration Worksi
 - ii Equipments/Tools being used in Restoration Works-
 - Procedure Taken up in Restoration Worksiii
 - iv Restored Length

Signature of JE/ AE/ EE

Signature (Name of Inspector)

EG

RWD WORK DIVISION muzastarpur Gast -1