FIELD INSPECTION REPORT

Di ti	te of Inspection: 20-12-2020 District: MALANDA),
Division	WAR WATER	ength (km): A. Con 1	40
Nameo	The Road: Not 110 P.M. G.S. y Road	to Nadiauna Poki	har Par
Package	TORTHUME: INTAME !	enstruction work	
		load Id No.:	
The same and the s			
Sl. No.	7 7 7 1		
	Parameters to be checked		Remarks
1.	Pavement		
n)	Road Junction condition		S/U ~
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/UV
d)	Road Camber		S/U V
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Ves/No
n	Contraction Joints provided or not (CC Pavement)		Yes/No V
g)	Compaction of flank/slope & raincuts if any		Yes/Nov
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b) ***	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	17

(Signature)

NAME: AJAY KUMAR VERMA
DESIGNATION: JUNIOR BAGINEEY