FIELD INSPECTION REPORT

Date of Ir	nspection: 2	1/12/2020 District: KichanganJ	
Division:	Kishan	9207 - 1 Length(km): 0.500	
Name of		adho hat tola to Losy.	***************************************
Scheme/	Programme:	GISNY	
Package	No.:	Road Id No.:	
Status of	the Project:	Ongoing/Completed /Under Maintenance	The second section of the second section of the second section of the second section s
Work is	Work is a case of: New Connectivity/ Up gradation / Maintenance		
S1. No		Parameters to be checked,	Remarks
1.	Pavement		VS/U.
a)	Road Junction Condition		1/5/U
b)			VS/U
c)	Riding Quality		1/S/U
d)	Road Camber S/U		~\$/U
e)		rom defects such as visible cracks, exposed aggregates	Yes/No
	in case of CC Pa	avement.	
f)		nts Provided or not (CC Pavement)	Yes/No
g)		flank / shop & raincuts if any	Yes/No
2.	Cross Drainage		
a)		ead walls in Hume pipe culverts including its Painting	S/SRI/U
b)		butment & Wing walls, slab in RCG culverts	S/SRI/U
c)		ilings/Slab/approach for Bridges	S/SRI/U
3.	Road Furniture		
a)		poards/informatory/cautionary Board/km & 200m	Yes/No
		ent road markings are provided and maintained	
4.	Status of ATR's		-
a)	Julia Ol AIN S	To drifty others	MP. 454.5

Overall Rating:

Satisfactory(S)	S	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory(U)	a	

(Signature)

NAME: Ray'eet Kloner

AE