FIELD INSPECTION REPORT

10 10 10 10 10 10 10 10 10 10 10 10 10 1	25, 1x*1.	TILLE INGI LUTIO	NREPURI	
Date of	Inspection: 91	12/20	District: East chan	bergy
Division	: Chatia		Length (Km): 0-630 km	4-100
	the Road : Tau			da
Scheme	Programme :	UTSNY		
Package	No.:		Road ID No.:	
Status of the Project : Ongoing/Completed/Under Maintenance				
Work is a	a case of :	New Connectivity/Up Gr		
SI. No.	Parameters to be checked			Remarks
1,	Pavement			
a)	Road Junction condition			S
b)	Condition of Surfacing			S
c)	Riding Quality			ک
d)	Road Camber			ک
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes
f)	Contraction Joints provided or not (CC Pavement)			Yes
g)	Compaction of flank/slope & raincuts if any			40
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts			, <del>-</del> 
c)	Condition of railings/slab/approach for Bridges			
3,	Road Furniture			
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained			No
4,	Compliance History			
a)	Status of ATR's & any others			
		O districtions (C)		
	Overall Rating :	Satisfactory (S) Satisfactory but requires improvement (SRI)		192
		Unsatisfactory (U)		t y' t a la salad
		Uliadia idocor y (0)		

NAME :

DESIGNATION:

(Signature)