## FIELD INSPECTION REPORT MMGSY (SC)

Date of Inspection: 15.12.20			District: Patua	
Division: Danabus			Length (km): 0.800 Km	
Name o	of the Road! MI		is devchand Bhagat T	ola to Bal
	:/Programme:	MAINTENANCE		3.9
Package No.:			Road Id No.:	
	of the Project:		/Under Maintenance	
	s a case of:	l	p gradation/ Maintenance	The state of
Sl. No.		Parameters to	be checked	Remarks
-11	Pavement			
a)	Road Junction condition			S/U
b)	Condition of S	S/U		
c)	Riding Quality	S/U		
d)	Road Camber			S/U
e)	Whether free aggregates in c	Yes/No		
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of tlank/slope & raincuts if any			Yes/No .
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
а)	Whether sign stones/Pavemen	Yes/Ne		
4.	Compliance History			
a)	Status of ATR's	& any others		

**Overall Rating** 

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Gignature)

NAME: chatubbly Mandel

DESIGNATION: JE