FIELD INSPECTION REPORT Date of Inspection: 21/12/20 Earl Chambasen District: Division: Chakia Length (Km): 1.50 Tasanli Passo Name of the Road: Chause Mallah CUTSHY Scheme/Programme: Package No.: Road ID No.: Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up Gradation/ Maintenance Remarks SI. No. Parameters to be checked 1, **Pavement** 5 a) Road Junction condition S b) Condition of Surfacing c) **Riding Quality** d) Road Camber Whether free from defects such as visible cracks, exposed aggregates in Yes e) case of CC Pavement. Yes f) Contraction Joints provided or not (CC Pavement) No g) Compaction of flank/slope & raincuts if any **Cross Drainage** 2. PLO SRI Condition of head walls in Hume pipe culverts including its painting a) Condition of Abutment & Wing walls, Slab in RCC Culverts b) Condition of railings/slab/approach for Bridges c) Road Furniture 3, Whether sign board/informatory/cautionary Board/Km & 200m No Stones/Pavement road markings are provided and maintained a) Compliance History 4. Status of ATR's & any others a) Satisfactory (S) **Overall Rating** Satisfactory but requires improvement (SRI) Unsatisfactory (U)

NAME :

DESIGNATION :