FIELD INSPECTION REPORT Date of Inspection: 21/12/20 East Chamberon District: nakia Division: 0.60 KM. Length (Km): Name of the Road: L021 Harijan tola Scheme/Programme: Package No.: Road ID No .: Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of : New Connectivity/Up Gradation/ Maintenance Parameters to be checked SI. No. Remarks 1, **Pavement** a) 5 Road Junction condition b) 5 Condition of Surfacing c) **Riding Quality** 5 d) Road Camber Whether free from defects such as visible cracks, exposed aggregates in Yes e) case of CC Pavement. Yes f) Contraction Joints provided or not (CC Pavement) NO g) Compaction of flank/slope & raincuts if any 2, **Cross Drainage** Yen Condition of head walls in Hume pipe culverts including its painting a) Condition of Abutment & Wing walls, Slab in RCC Culverts b) Condition of railings/slab/approach for Bridges c) 3. Road Furniture Whether sign board/informatory/cautionary Board/Km & 200m Yen Stones/Pavement road markings are provided and maintained a) Compliance History 4.

Overall Rating

a)

Status of ATR's & any others

	1,0,
Satisfactory (S)	1 3
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME :

DESIGNATION :