FIELD INSPECTION REPORT

-	de la la	FIELD INSPI	CHON REPORT	
Date o	Inspection: 2	1		
Divisio	11: R-W-D	Dutos 200	District: Buyar . Length (km): 1.80 Km	
Name	of the Road; No	Massagn	Length (km): 1.80 Km	
Schem	c/Programme:	MAINTENANCE	month soud to Chy	al radi
-			Road Id No.:	ak soo
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work	s a case of:		Up gradation/ Maintenance	
SI. No.		Parameters to	be checked	Remarks
1.	Payement			
a)	Road Junction condition			√8/U
b)	Condition of Surfacing			√S/U
c)	Riding Quality			√S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainag	c. And the second		Contract of the Contract of th
a)	Condition of head walls in Hume pipe culverts including its painting			SSRITU
b) -	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c) .	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yex/No
4.	Compliance Hi	story	Figure 1 to 100 to 100 to	Barting St.
a)	Status of ATR's	THE RESERVE AND ADDRESS OF THE PARTY OF THE		
-	THE RESERVE OF THE PARTY OF THE PARTY.	The state of the s		ACCRECATE VALUE OF THE PARTY OF

Overall Rating

100 26 1121-100

Satisfactory (S)	11511
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

2012 2020 PE

(Signature)

NAME:

DESIGNATION:

Scanned with CamScanner