## FIELD INSPECTION REPORT

vate of fr	ispection: 2	6.12.2020	District: Buxar	
Division :	R-W-D.	Dutorgon	Length (km): 1.10 KM	
Name of	the Road: De	ata Debri	pultoonep Khung Pe	35WAD
The same of the same of	Programme:	MAINTENANCE	Road Id No.;	
Package		On sing Complete	ed/Under Maintenance	
	the Project:	And a second sec	/Up gradation/ Maintenance	
Sl. No.	The same of the sa		o be checked	Remarks
1,	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			√S/U
c)	Riding Quality			SIU
d)	Road Camber			S/U
e)	Whether fre aggregates in	Yes/No		
f)	Contraction Joints provided or not (CC Pavement)			Xes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/L
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/I
3.	Road Furniture			1
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance	Compliance History		
a)	Status of AT	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	400
Unsatisfactory (U)	SRI

25/12/2000

(Signature)

NAME:

Scanned with CamScanner