	FIELD INSPECTION REPORT	
DATE OF INSPECTION:	22/12/2020 DISTRICTI PURULA	
DIVISION:	Déandala IENOTIN 2.658 KM	
NAME OF THE ROAD!	Too to Brokman Tola	
SCHEME/PROGRAMME:	PM.GISY MAINTENANCE	
PACKAGE No:	IIOAD ID No.I	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAKINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GIRODATION/MAINTENANCE	
\$L.NO	PARAMETERS TO DE CHECKED	REPARKS
1	PAVEMENT	101
Α	ROAD JUNCTION CONDITION	'S'
	CONDITION FO SURFACING	'υ' .
	RIDING QUALITY	`S'
0	ROAD CAMBER	
	WHETHER FREE FROM DEFECTS SUCH AS VISIDLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	`3'
t		`S'
	CONTRACTION JOINTS PROVIDED OR NOTICE PAVEMENT)	ア,
G	CROSS DRAINAGE	
2	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS	`S'
	PAINTING	<i>'s'</i>
A	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N.A
B	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	14.77
<u> </u>	ROAD FURNITURE	
3	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M	' S'
Α 🐷	TONES PAVEMENT ROAD MARKING	
4	COMPLIANCE HISTORY	N, A
A	Status OF ATR": B ANY OTHERS Some part Of B. T Surface is a	lamaged
OVERALL RATING		
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	70'
	UNSATISFACTORY(U)	المندوري
	VIII	22/12/2

NAME: Surandora prosad Singh DESIGNATION: Junior Engineer SIGNATURE