

FIELD INSPECTION REPORT

Date of Inspection: 30-12-2020		District: GAYA	
Division: Narmada Bathani		Length (Km.): 0.325	
Scheme/Programme:		MAINTENANCE	
Package No.: 2019-2020		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked		Remarks
1	Pavement	S	S/U
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes	Yes/No
g)	Compaction of flank/slope & raincuts if any	No	Yes/No
2	Cross Drainage	NA	S/SR/U
a)	Condition of head walls in Hume pipe culverts including its painting	NA	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	S/SR/U
c)	Condition of railings/slab/approach for Bridges	S	S/SR/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes	Yes/No
4	Compliance History		
a)	Status of ATR's & any others.		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SR)	SAI
Unsatisfactory (U)	

Chhote Pail
30-12-2020
T.E