Inspection Report for Flood Damage Work

Date:

- 1. Piame of PIUs Crycin vibhalous
- 2. Name of Block/Road Kadra / Tos to sonpul

A Fer Road

- 1. Damage Location/Chainage
- : 0.240km, 0.400km, 0.900km, 0.930km, 1,00km,

- 2. Damage Length
- : 0.055Km (AProx)
- 3. Nature of Damage
- \$ (0.0545 km)
- 4. Details of Restoration Works
 - Material being used in Restoration works: Brick ball & Local Sand
 - Equipments/Tools being used in Restoration works: ii.
 - Procedure taken up in Restoration works: iii.
 - iv. Restored Length
- >0.013 icm (AAM)

B. For Bridge

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
 - Material being used in Restoration works:
 - Equipments/Tools being used in Restoration works:
 - Procedure taken up in Restoration works: iii.
 - Restored Length iv.

Light lire

(Name of Inspector)

EF

RWD WORK DIVINGON muzaffers Dur Galt-1

Signature of JE/AE/EE