


FIELD INSPECTION REPORT

Date of Inspection: 24.12.2020	District: Samastipur	
Division: RWD Dalsinghsarai	Length(km): 0.526 km	
Name of Road: Cross Path Mahthi to Tanna Tanachak		
Scheme / Programme:	MAINTENANCE	
Package No: MM684	Road Id No:	
Status of the Project: <u>Ongoing</u> / Completed / Under Maintenance		
Work is a case of: <u>New Connectivity</u> / Up gradation / Maintenance		
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	SPT
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridge	-
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	SPT S
4	Compliance History	
a)	Status of ATR's & any others	M.


Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SPT
Unsatisfactory(U)	


24.12.2020
(Sign: arc)

NAME:

DESIGNATION :



65