FIELD INSPECTION REPORT

	TILLD INST LC	71101111	
Dat	te of Inspection: 24.12.2020 District: Samastipur		
Div	Division: RWD Dalsinghsarai Length(km): 1.31		~
Nai	ne of Road: paroriya to chale milke		
	eme / Programme: MAINTENANCE		
	kage No: 14M G184		
Stat	us of the Project: Ongoing/Completed/Under Mai	intenance	
-	rk is a case of: New Connectivity/ Up grada	ation/ Maintenance	
SI. No	Parameters to be Checked		Remarks
1	Pavement		
a)	Road Junction Condition		
b)	Condition of Surfacing *		5
c)	Riding Quality		5
d)	Road Camber		>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		. 5
f)	Construction Joint provided or not(CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		S
2	Cross Drainage		
	Condition of head walls in Hume pipe culverts including its painting		MA
a)	Condition of Abutment & Wing walls, Slab in Re	CC culverts	M.A
b)	Condition of railings/slab/approach for Bridge		N. A
3	Road Furniture		
	Whether sign boards/information/cautionary Boar stones/Pavement road markings are provided and	d/km & 200m maintained	5
	Compliance History		10.
)	Status of ATR's & any others		И.

Overall Rating :

Satisfactory(S)	2
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

(Signa are)

NAME: April present DESIGNATION: