FIELD INSPECTION REPORT

	TILLED IN OF LETTON KET OKT	
ate	of Inspection: 36.12.2020 District: Samastipur	
	ion: RWD Dalsinghsarai Length(km): 0 540 km	
lam	e of Road: Lohage's path to Sarpanch Tola muching Tola	2
che	me / Programme: MAINTENANCE	
ack	age No: MMGSY Road Id No:	
tatu	s of the Project: Ongoing/Completed/Under Maintenance	
Vorl	is a case of: New Connectivity/ Up gradation/ Maintenance	
il.	Parameters to be Checked	Rema.ks
	Pavement	
1)	Road Junction Condition	2
)	Condition of Surfacing *	2
2)	Riding Quality	3
(b)	Road Camber	2
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Construction Joint provided or not(CC Pavement)	2
g)	Compaction of flank/slope & raincuts if any	SPJ
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting -	a. b
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	M.A
c)	Condition of railings/slab/approach for Bridge	a.A
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	3
4	Compliance History	
a)	Status of ATR's & any others	N

Overall Rating :

Satisfactory(S)		
Satisfactory but requires Improvement(SRI)	SPS	
Unsatisfactory(U)		

(Signa are)

NAME: Anil Prague