

पत्रांक:- 964/3133)

मसौदी/दिनांक:- 16.10.2020

प्रेषक :

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल मसौदी।

सेवा में,

अधीक्षक अभियंता
ग्रामीण कार्य विभाग,
कार्य अंचल, पटना।

विषय:-वर्ष-2019 के बाढ़ में क्षतिग्रस्त पथों को मोटरेबुल करने हेतु किये गये कार्य की जाँच के संबंध में।

प्रसंग:-विभागीय पत्रांक-मु0अ0-4 (मु0) विविध (कार्य)-23-291/2019-3976 दिनांक-11.09.2019
एवं भवदीय पत्रांक-1481 दिनांक-15.09.2020

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र के निर्देश के आलोक में ग्रामीण कार्य विभाग, कार्य प्रमंडल दानापुर का निम्नलिखित दो पथों का दिनांक-13.10.2020 को बाढ़ क्षतिग्रस्त मरम्मत कार्य का जाँच किया गया एवं किया गया कार्य संतोषप्रद पाया गया।

सूचनार्थ समर्पित।

क्रमांक	पथ का नाम	पथ की लम्बाई	क्षतिग्रस्त पथ की लम्बाई
1	सर्वोदय सिटी आदमपुर से लखनी बिगहा पथ	0.600	0.450
2	मुख्य खगौल रोड बटाला से आदमपुर मुशहरी तक जाने वाली सड़क	1.100	0.900

अनु0:- निरीक्षण प्रतिवेदन प्रपत्र संलग्न।
(दो प्रतियों में)

विश्वासभाजन

16/10/2020
कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल मसौदी।

Inspection Report for Flood Damage Work

Date:....13/10/2020

1. Name of PIU:- Executive Engineer, R.W.D(W) Division Darnapur
2. Name of Block/Road:- Darnapur / Main Khajaul Road Bata,la to
3. For Road:- Adampur Mushari Jane wali Road.
4. Damage Location/Chainage:- Ch. 0m to 750 m and 950 m to 1100 m
5. Damage Length:- 900 m
6. Nature of Damage:- Damage due to heavy Rain
 - I. Material being used in Restoration Works:- Brick Bats
 - II. Equipments/Tools being used in Restoration Works:- J.C.B, Tractor, Roller
 - III. Procedure taken up in Restoration Works:- Brick bats laying, spreading and Compacting.
 - IV. Restored Length:- 900 m

B. For Bridge

1. Damage Location/Chainage:-
 2. Damage Length:-
 3. Nature of Damage:-
 4. Details of Restoration Works:-
 - I. Material being used in Restoration Works:-
 - II. Equipments/Tools being used in Restoration Works:-
 - III. Procedure taken up in Restoration Works:-
 - IV. Restored Length
- N/A

13/10/2020
Name of Inspector
Executive Engineer
R.W.D Works Division
Masaurhi