

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar

2. Name of Block/Road - mirapur/ Belahi Luchi Raabur talu to Hryatal seni
mandal via Kusmi talu

✓ A. For Road

1. Damage Location/Chainage : 0.100km, 0.150km, 0.200km, 0.500km, 0.600km, 0.750km, 0.900km

2. Damage Length : 0.132km

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works : Brick ball & local sand

ii. Equipments/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works :

iv. Restored Length : 0.132km

✗ B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Signature of JE/AE/EE


18-11-20
Signature

(Name of Inspector)

EE

RWD works division

munaffapur East - I

GENERAL ABSTRACT

Name of Road Belahi Lachhi Rajput Tola to Hiyalal Devi Mandir via Kurmi Tola

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km)

1.529 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Jhama metal	4.095
3	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	4.095
TOTAL COST OF PROJECT IN LACS =		4.095

[Signature]
11/11/20

JE
RWD

[Signature]
11/11/20

AE
RWD

[Signature]
11/11

EE
RWD

Technically approved for RS 4.095 lac
(Rupees Four lac Nine thousand five hundred only)

[Signature]
28/12.20
S.E

RWD work circle
muzaffarpur