## Inspection Report for Flood Damage Work

Date:
1. Name of Plus - KWV normande - chero PWD Path Ke Vegation
2. Name of Block/Road- Norgan Win Bliddli Jagathur, July
1. Name of PIUS - RWD Har naut  2. Name of Block/Road - Nongarnousa - churo PWD Path Ke vezapali to  2. Name of Block/Road - Nongarnousa - churo PWD Path Ke vezapali to  A. For Road Sindiusa village via Chridoli, Jagathur, Jiranfur
1. Damage Location /Change- 1.680km A.720km, 0.840 Em
2. Damage Length- 0.054 K, M, Land
2. Damage Length- 3. Nature of Damage- Heavy Pain Thoof
4. Details of Restoration Works-
i. Material being used in Ristoration works- Brick Bot ii. Equipments/Tools being used in Restoration works- JCB, Tooli, Tools, Puller, etc. iii. Procedure taken up in Restoration works-
ii. Equipments/Tools being used in Restoration works- JCB, 18000, 180000, 180000
iii. Procedure taken up in Restoration works
iv. Restored Length-  B. For Bridge  O. 054 Km

- 1. Damage Location / Chainage-
- 2. Damage Length-
- 3.Nature of Damage-
- 4. Details of Restoration Works
  - i. Material being used in Restoration work-
  - ii. Equipments/Tools being used in Restoration Work-
  - iii. Procedure taken up in Restoration work-
  - iv. Restored Length-

## C. Requirement Of New CD/Bridge

- i. Name of Road-
- ii. Location Chainage-
- iii. Type of CD work/Length required
  - Upload one photograph of damaged portion if available
  - Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode

Signature of JE/AE/EE

NU14 23-1-2021 AR

Signature