

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar
2. Name of Block/Road - mirapur/pakhaha to pusaana tal.


A. For Road

1. Damage Location/Chainage : 0.0201km, 0.1101km, 0.200km, 0.3401km, 0.6001km, 0.700km
2. Damage Length : 0.35451km 0.800km
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : brick ball & local sand
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.3545 km

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE


21.12.20
Signature

(Name of Inspector)

EE
RWD work division
muzaffarpur East-1