

Schedule XLY-Form No. 134

FDR (2020-21)

N.B. No - 28

DIVISION

lost to Tarasmi Muni tola

SUB-DIVISION

Black - Dharmdaha

Measurement Book

Name to work— 1
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NAME OF WORK:- Restoration of Road L. 57 to Tanawhi Muni Tal. n.					
Authority:- U.C.R.W.D.					
Work Division, Dharmadaha.					
1- Providing and Laying R.C.C Pipe No. 2 1000 Ø (MM) in single Row					
4 No. 1 X 2.50 M = 10 Meters					
2 Supply and spreading of Brick Ball					

350M-	5 M X	(4.00 + 6.70) M		
		2		
	X	(0.90 + 1.60 + 1.90 + 0.80) M		
		4		
				= 35.10 M ³
370M-	3.80 M X	(4.05 + 7.12) M		
		2		
	X	(1.80 + 1.60 + 1.20) M		
		3		
				= 32.54 M ³
				T = 67.64 M ³

Purnea
 29-11-2020
 (J.B.)

~~30/11/20~~

29/12/20

Executive Engineer
 Rural Works Department

Works Division Dharmadaha (Purnea)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(ABSTRACT OF COST)					
1/1 supply and spreading					
Brick ball Dth					
67.64 m ² vide					
on P.O. item N.					
(02) @ 12/-					
1717 = 27/ m ²					
					B. 1,16,163
2/2 providing and Laying					
R.C.C. Pipe 100 mm					
8 in single row					
10 m ² on P.O.					
item N. (01) @					
D. 4432 = 83/m ² 44,382					
					D - 5,69,491.2

Add G.S.T. 12% (+) 1,92,580.2				
Add Labour 10% (+) 16,652.0				
Add S. fee — (+) 22,000.0				
Total 1,80,000.2				

By REDA
26/02-22
J.D

Continuation

Inspection Report for flood damage work

Date:

1. Name of PIUs- Dhamdaha

2. Name of Block/Road- LO57 to Taruni Muni Tolg

A. For Road

1. Damage Location/Chainage :

2. Damage Length : 8.80m

3. Nature of Damage : Top surface washout due to flood

4. Details of Restoration :

i. Material being used in Restoration — Brick Bat, Hume pipe

ii. Equipment/Tools being used in Restoration works: Tractor

iii. Procedure taken up in Restoration works : manu

iv. Restored Length : 8.80m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i. Material being used in Restoration :

ii. Equipment/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works :

iv. Restored Length :

P. Kumar
27-07-22
Signature of JE/AE/EE

27/7/22
AE

27-1-21
EE

Signature P. Kumar
(Name of Inspector) 27/7/22