## INSPECTION REPORT FOR ROUTINE MAINTENANCE

	on: Maraura Length (km): 0.90	
		Tola Hole Hue
Schem	of the Road: Salgera Prittiput Muchya Sadak To Sakwar Pritting pur Primary School tak	
Sl. No.		Remarks (S/U)
1.		
SALES BOOK	AND THE PROPERTY OF THE PROPER	S
a)	Condition of Surfacing	, 5
b)	Riding Quality	
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
2.	Cross Drainage	1
Mary St. Ton College	The state of the s	
		1 24
a)	Condition of head walls in Hume pipe culverts including its painting	
a) b)	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts	-
a) b) c)	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges	-
a) b) c) d)	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance	-
a) b) c) d)	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges	-
a) b) c) d) eservat	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance	-
a) b) c) d) eservat	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance  tion Remarks:-  C.D. not found	- - - - S
a) b) c) d) servat	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance  tion Remarks:-  C.D. not found  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m	- - - - S
a) b) c) d) servation	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance  tion Remarks:-  C.D. not found  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m tones/Pavement road markings are provided and maintained	5

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Sin Kant Prased. Name of Officer:-

Designature:- E.E.

S00 31/7/2021 A.E. 311712021 (Signature)