INSPECTION REPORT FOR ROUTINE MAIN LENANCE

Date of	Inspection: 0	1/08/2021	Length (km): 2.825 Len	
n			Length (km): 2.825 len	Colhallus 104
	the Road: Lo	192 - From Ja	mal Por South to Kathaiya higo	1 Server (V) - 100
Scheme/Programme: Routine Maintening Sl. No. Parameters to be checked			Remarks (S/U)	
Sl. No.		The state of the s	MINI PLANTING	
1.	Pavement			S
a)	Condition of Surfacing			
b)	Riding Quality			<u>S</u>
c)	Road Camber			
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			5
e)	Contraction Joints provided or not (CC Pavement)			2
f)	Compaction of flank/slope & raincuts if any			5
2	Cross Draina	ge		
2.	Cross Drainage Condition of head walls in Hume pipe culverts including its painting			NIA
a)	Condition of head walls in Hume pipe curvers in Fig. 7 Condition of Abutment & Wing walls, Slab in RCC culverts			3
b)	Condition of Abutment & Wing Wans, Side in Yes Condition of railings/slab/approach for Bridges			NA
c)	Condition of Vent Clearance			3
<u>d)</u>				
Observa	Z,	co, culver	l'is in good Condition	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained			
Observ	ection Remarks	:- Proud Fue	is from in Rue), K. M. Post
4.	Compliance History		Δι. Δ	
<u> </u>	Status of ATR's & any others		NIA	
a)	Status 01			2
	ll Rating of Officer:-	Satisfae Radnesh Pa	ctory (S)/ Unsatisfactory (U)	ignature)