## INSPECTION REPORT FOR ROUTINE MAINTENANCE

121011 :	Reliand Length (km): 0.165	
me of t	Belsand Length (km): 0.165 he Road: Mushhari Harizon Colony to TOI.	
water the same of the same of the same	rogramme: 6TSNY	
No.	Parameters to be checked	Remarks (S/U)
-	Pavement	
	Condition of Surfacing	5
	Riding Quality	S
	Road Camber	S
c) d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	5
e)	Contraction Joints provided or not (CC Pavement)	کہ
f)	Compaction of flank/slope & raincuts if any	ی
2.	Cross Drainage	No entre
		No culve
	Condition of head walls in Hume pipe culverts including its painting	. —
a)	Condition of Abutment & Wing walls, Slab in RCC culverts	7
b) c)	Condition of railings/slab/approach for Bridges	1
d)	Condition of Vent Clearance	_
	vation Remarks:-	
	Road Furniture	
Observation 3.	Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	3
Observation 3.	Road Furniture  What has sign boards/informatory/cautionary Board/ km & 200m	3
Observation 3.	Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained  vation Remarks:-  Compliance History	
3. a) Observ	Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained vation Remarks:-	NO ATR