C.C: Mukesh Kumar Singh

INSPECTION REPORT FOR ROUTINE MAINTENANCE

ate of	Length (km): 7.39 Km	
Vame o	sup Dood Ropair of Road from NH-77 ald Bindewar	Asthan to
	Programme: MR	
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	V
b)	Riding Quality	V
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Pot	halos seen en BT Porton in different char	nage
Pot	halos seen en BT Porton in different char	nage
Pot	halas seen en BT Porton in different chat Cross Drainage	noge
William I.	Cross Drainage	nage S
2.		
2. a)	Cross Drainage Condition of head walls in Hume pipe culverts including its painting	S
2. a) b) . c) d)	Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance	S
2. a) b) . c) d)	Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges	S
2. a) b) . c) d)	Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance	S
2. a) b) c) d) Observ	Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance Pation Remarks:-	S
2. a) b) c) d) Observ	Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance vation Remarks:- Road Furniture Whether sign boards/informatory/cautionary Board/ km & 200m	S
2. a) b) c) d) Observ	Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance Pation Remarks:- Road Furniture Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Overall Rating

7.

Satisfactory (S)/ Unsatisfactory (U)

Name of Officer:- RANCESH KINGTON ग्रामीण कार्य विभाग Besignature:- कार्य अंचल, पटना