INSPECTION REPORT FOR ROUTINE MAINTENANCE

ivision	Inspection: 16.12.2021 District: Katikar Length (km): 0.500	
THE RESERVE AND PERSONS ASSESSED.	1 the Road: Rangpera to Thaker Tola	
cheme	Programme: GTSNY	
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	5
b)	Riding Quality	5
c)	Road Camber	5
ď)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<u>S</u> <u>S</u>
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any no van lak	S
	ation Remarks:- Subject Condition is Satisfactory.	
2.	Cross Drainage	
i kapa		
2.	Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls Slab in PCC culverts	
2. a)	Cross Drainage Condition of head walls in Hume pipe culverts including its painting	
2. a) b) c) d)	Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance	
2, a) b) c) d) Observ	Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance vation Remarks:-	
2. a) b) c) d)	Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance vation Remarks:-	
2, a) b) c) d) Observ	Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance vation Remarks:-	<i>S</i>
a) b) c) d) Observ	Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance vation Remarks:- Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m	
a) b) c) d) Observ	Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance vation Remarks:- Road Furniture Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	

Satisfactory (S)/ Unsatisfactory (U)

Name of Officer. Rana Basun Kumar Singh Designature: - Executive Engineer, Regional Lat. Blagelyur.

Setulatory (S)