

INSPECTION REPORT FOR FLOOD DAMAGE WO

Date :

1. Name of PIUS :- R.W.D works Division Harnaut.
2. Name of Block/Road :- Harnaut - NH304 Baharainpur chattri Road to Abbanahmadpur R.W.D Rec

A. For Road :

1. Damage Location/Change :- ^{AT} CH- 400m, 470m, 610m, 730m, 920m
2. Damage Length :- Total - 48.0m ✓
3. Nature of Damage :- Flank Damage
4. Details of Restoration Works :- Sand bags
 - i. Material Being used in Restoration works :- Sand, Cement empty bags,
 - ii. Equipment's / Tools being used in Restoration works :- Tractors, J.C.B.
 - iii. Procedure taken up in restoration works :-
 - iv. Restored Length :-

B. For Bridge :

1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - i. Material Being used in Restoration works :-
 - ii. Equipment's / Tools being used in Restoration works :-
 - iii. Procedure taken up in restoration works :-
 - iv. Restored Length :-

C. Requirement of New CD/Bridge :

- i. Name of Road :-
- ii. Location Chainage :-
- iii. Type of CD work/Length required :-

- Upload one photograph of damaged portion if available


•


- Attach minimum two photograph (during restoration & after restoration) photographs Geotags and at least one photo be captured in selfie mode.

Signature of


JE


AE


EE


Executive
Rural Works
Works Div