

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- Aurai / Bhairo Asthan (Teka) more to Bagatapur  
more hote hue Murasha Path.

(A) For Road:

1. Damage Location/Chainage :- many places
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- Brick bats
  - (ii) Equipment's/Tools being used in Restoration works:- Tractor
  - (iii) Procedure taken up in Restoration works:
  - (iv) Restored Length :-

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

  
Signature

(Name of Inspection)

कार्यपालक अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1

## GENERAL ABSTRACT

Name of Road            Bhairo Asthan (Teka) More to Basatapur More Hue Muraaha Path

District                    Muzaffarpur

Block                      Aurai

Division                  Muzaffarpur East-2

Length of Road (in Km)

5.700 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	13.654
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	13.654
TOTAL COST OF PROJECT IN LACS =		13.654

*SEY*  
11/11/21  
JE  
RWD

*AE*  
11/10/14  
AE  
RWD

*EE*  
11/11  
EE  
RWD

Technically approved for Rs 13.654 lac  
(Rupees Thirteen lac sixty five thousand four  
hundred only)

*11/11/21*  
अधीक्षक अभियंता  
ग्रामीण कार्य विभाग  
कार्य अंचल, मुजफ्फरपुर