Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs: - Gyan vivatar

2 Name of Block/Road: - Awai / Improve ment of puprimore to minapur Hospital

(A) For Road:

(A) For Road:

- 1. Damage Location/Chainage :- many places.
 2. Damage Length :- 0.43405 Km
- 3. Nature of Damage

4. Details of Restoration Works :-

- Material being used in Restoration works:- Brick bats (i)
- Equipment's/Tools being used in Restoration works:- Tracfor. (ii)
- Procedure taken up in Restoration works: (iii)
- :- 0.43405 Kon Restored Length (iv)

(B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works :-
- Material being used in Restoration works:-
- Equipment's/Tools being used in Restoration works:-(i) (ii)
- (iii) Procedure taken up in Restoration works:- .
- (iv) Restored Length

Signature of JE/AE/EE

Signature 2

(Name of Inspection) कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल,मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road

Improvement of Pupri More to Minapur Hospital More Via Khetalpur and Baraitha Road

District

Muzaffarpur

Block

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

4.465 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	8.786
2	Sand Filling	0.000
3		0.000
3	Sand bag	0.000
4	H.P.	8.786
	GRAND SUB TOTAL	8,786

See 1111121

JE RWD Molifolly

AE

EE

RWD

Technically approved for AS 8-786 Lac
(Rupees Eight lac seventy Eight thousand
six hundred only)

अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल,मुजफ्फरपुर