Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs: - Cyan Vibrakor

2 Name of Block/Road: - Auroi / Horpur to Amnaur

(A) For Road:

- 1. Damage Location/Chainage :- 0.20 1m, 0.301m, orsnim
- 2. Damage Length :- 0.2184 lan
- 3. Nature of Damage
- 4. Details of Restoration Works:
- Material being used in Restoration works:- Brick both (i)
- Equipment's/Tools being used in Restoration works:- Tractor. (ii)
- (iii) Procedure taken up in Restoration works:
- (iv) Restored Length :- 0.2184 Im

(B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works:
- Material being used in Restoration works:-(i)
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल,मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road

Harpur to Amnaur

District

Muzaffarpur

Block

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

SI. No.	DESCRIPTION	8.937 Km
-1	Earthwork	AMOUNT (LAKHS)
2	Jhama metal	0.000
3	Sand Filling	6.771
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	0.000
TOTAL COST OF PROJECT IN LACS =		6.771
10.913	14 LAC3 =	6.771

JΕ

RWD

18 Mills

ΑE

RWD

EE 20) 1

Technically approved for RS 6.771 lac (Rupers six bal seventy seven thousand one hundred only)

अधीक्षण अभियंता प्रामीण कार्य विभाग

कार्य अंचल,मुजफ्फरपुर