## **Inspection Report for Flood Damage Work**

D	ate	:	_

1 Name of PIUs: - Gyan Vibhakar

2 Name of Block/Road: - Aurai | Construction of Ashmanpur peo Salak to Borbara

(A) En Dood.

Cawan Hote hue Sorhahira tak Salak Hirman.

- 1. Damage Location/Chainage :- or 100 land, or 100 land
- 2. Damage Length :- 0.106212
- 3. Nature of Damage
- 4. Details of Restoration Works:
- (i) Material being used in Restoration works:- Brick bat
- Equipment's/Tools being used in Restoration works:- Tractors. (ii)
- (iii) Procedure taken up in Restoration works:
- (iv) Restored Length 01062lan

## (B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works:
- Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल,मुजफ्फरपुर पूर्वी-1

## **GENERAL ABSTRACT**

Name of Road

Construction of Ashmanpur REO Sadak to Borbara Gawan Hote Hue Sarhahiva Tak Sadak

District

Muzaffarpur

Block

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

2.220 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Jhama metal	2.019
3	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	2.019
OTAL COST OF PROJECT IN LACS =		2.019

RWD

Technically approved for RS 2.019 lac (Rupees two lac one thousand nine hundred only)

अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल,मुजफ्फरपुर