

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- Aurai / Lobo To 8 to Basi Baijnath ali Nagar (VR 35)


(A) For Road:

1. Damage Location/Chainage :- 0.52010m, 0.62010m & 0.72010m
2. Damage Length :- 0.14783 Km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor.
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- 0.14783 Km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road L060 T08 to Basi Baijnath ali Nagar (VR35)
District Muzaffarpur
Block Aurai
Division Muzaffarpur East-2
Length of Road (in Km) 3.770 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Jhama metal	16.068
3	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	16.068
TOTAL COST OF PROJECT IN LACS =		16.068

524
11/11/21
JE
RWD

11/11/21
AE
RWD

11/11/21
EE
RWD

Technically approved for Rs 16.068 lac
(Rupees sixteen lac six thousand eight hundred only)

11/11/21
अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर